USS LOWNDES (APA-154) SHIP'S HISTORY CALENDAR 2004

60th Anniversary



Data for this Calendar comes from the Ship's deck log and personal diaries of Calvin Bull and Fred Brinkman.

Please contact David Brinkman for additions or corrections. Note: Not all Lowndes crewmen are documented in this calendar. Initially, we tried to include all crewmen that are members of the reunion group. The deck log is not a 100% accurate source for crewmen arrivals and departures so not all crewmen are represented in this respect. Please let us know if you have missing information so that it can be added to future Calendars. Thanks.

For much more, visit the USS Lowndes Web Site at:

www.usslowndes.net

and see:

Lowndes' Memorial to Norman Richards and Don Bowman USS Lowndes Narrative History The USS Lowndes' Route (Animated Map) Personal Accounts and Logs USS Lowndes Online History Calendar 2004 USS Lowndes Deck Log Marines on the Lowndes WWII Pictures and Items brought home by the Lowndes crew War Video/Audio and Songs Reunion Pictures Reunion Videos Lowndes' Reunions (Future and Past Reunions with attendance stats) Lowndes Newsletters (By Bud Kautz) and Site Search Lowndes Blue Prints and models APA Historical Preservation Project - Save the Gage Books and Movies about APA's The USS Lowndes Games Other Attack Transport Sites Lowndes Guestbook for Visitors to sign Web Site Change History



U.S.S. LOWNDES (APA-154) JANUARY 2004

The Ship's History Calendar

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				1 1945 - Maui - Paravane & Pyrotechnic exercises. Lost Steering control. 1946 - Headed to Manila.	2 1945 - Landing Practice with smoke screen. 1946 - Changed course to Hawaii.	1946 - Arrived at Pearl Harbor. Captain Perdue leaves ship for hospitalization.
4	5	6	7	8	9	10
1945 - Moored in Berth at Pearl Harbor between APA-158 and AKA-91.	days solitary with only	1945 - Gun Practice with towed sleeve target. 1946 - Moored next to Dock A-12, Pearl Harbor.	1945 - Landing practice: All Boats + Troops away. 1946 - Mustered crew at quarters. No absentees.	1945 - Landing Practice with Beach Party. Fire in Engine room.	1945 - Gun Practice. William Bornhorst arrives on Lowndes.	1945 - Paul Lineback arrives on the Lowndes. 1946 - Edward Mable unde Court Martial.
11	12	13	14	15	16	17
1945 - In Berth X-11, East Lock, Pearl Harbor. 1946 - D. J. Weintraub takes over as Captain.	1945 - Paravane Exercises. 1946 - GQ to fix problem with mooring lines.	1945 - Landing exercises + LCVP smoke boat drill. 1946 - Daily inspections. Conditions normal.	1946 - New Captain cracks down on uniform violations. Fire in A101. 10 mattresses lost.	Boat #13 does not return.	1945 - Practice: All Boats away. Simulate taking aboard casualties.	1945 - Fire in #2 Hold. 1946 - Traveling alone from Pearl Harbor to San Francisco.
18	19	20	21	22	23	24
1945 - Moored in Berth at Pearl Harbor between APA-119 and APA-156.	sick Marines to Hospital.	1946 - Empty life raft found drifting in ocean. Raft inspected and course resumed.	1946 - Arrived in San Fran. Cliff Schaffer, Glenn Forgay, and Francis Miller transfer off Lowndes.	1946 - Vincent Rizzo transferred off the Lowndes.	1945 - Loaded 93432 gallons of fresh water. 1946 - Moored next to USS Prometheus.	1946 - Moored next to US Prometheus (AR-3) at Sar Fran. anchorage #9, berth #18.
25	26	27	28	29	30	31
1945 - Motion Picture Projectionist arrives. 1946 - Completed below deck insoections.	1945 - Received ammo from LCM. 1946 - Fred Gideon detached from Lowndes.	1945 - Left Pearl Harbor for Eniwetok Atoll. 1946 - 3 camels between Lowndes and Prometheus.	1945 - Executed emergency turns. 1946 - Burning truck and anchor lights.	1945 - Recovered fouled Paravanes. 1946 - Collision with LST-168 in San Fran Bay.	1945 - Fire drill and emergency maneuvers. 1946 - Engine room is on repair orders.	1945 - Gun practice at a radio controlled plane. 1946 - James Chilcote, Alonzo Hodgson, and
						Arvil Sefers detached fror the Lowndes on January 3 1946.





U.S.S. LOWNDES (APA-154) FEBRUARY 2004

The Ship's History Calendar

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1 1945 - Enroute from Pearl Harbor to Eniwetok Atoll.	2	3 1945 - Tactical maneuvers and zig-zagging.	4 1945 - Gun practice and Streamed Paravanes.	5 1945 - Arrived at Eniwetok Atoll. Water Main Burst		7 1945 - Left Eniwetok for Saipan. Simulated air attack. 3 men wounded by gun shrapnel (F. Wanits)
8 1946 - On way from San Francisco for Balboa, Canal Zone (Panama Canal).	9 1945 - Drills: Fire and	10 1945 - Tactical Maneuvers for Photographic purposes.	1945 - Arrived at Saipan. Men transferred for LST training.	1945 - Gun Practice for Ship's Officers (.45 cal). 1946 - Man over board drill.	13 1945 - Lying in transport area off T inian Island. 1946 - Abandon ship drill.	1945 - Anchored with other Pacific Fleet ships surrounded by antisub net. 1946 - Abandon ship drill.
15 1945 - Smoke Boats in Water and working. (Boats #19, #20, "R", and LCM-24).	16 1945 - Headed to Iwo Jima. Emergency Turn to avoid Enemy Sub. 1946 - In Panama Canal	1946 - Anchored in berth 23 in Limon Bay, Canal Zone.	1945 - Emergency turns ordered to avoid enemy submarine contact.	1945 - Arrived at Iwo Jima 0645 (D-Day). Debarked Troops. Many casualties received.	20 1945 - Beach party lands and has 14 wounded. Norman Richards and Don Bowman are lost (KIA.)	21 1945 - Enemy Aircraft in Area. More casualties received from Iwo Jima.
22 1945 - More casualties received from Iwo Jima. 1946 - Left Limon Bay for Norfolk, Virginia.	23 1945 - Enemy Aircraft in Area. 1946 - Lowndes cuts the Atlantic for the first time.	24 1945 - Debarked 24th Marine Replacement. Beach party returns. 1946 - Strong Strom	25 1945 -Casualties received. Embarked 101 men of 24th Marine Rep. Dick Jones injured on ship.	26 1945 - More casualties received from Iwo Jima. 1946 - All engines stop. Leak in main air injector.	27 1945 - Ship's position given relative to Flag on Surabachi. 4 LCVPs from APA-30 put on Lowndes.	28 1945 - Left Iwo Jima for Saipan with 321 wounded. 1946 - Arrived at Pier #9 Newport News, VA.
29						





U.S.S. LOWNDES (APA-154) MARCH 2004

The Ship's History Calendar

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
	1	2	3	4	5	
	1945 - Enroute from Iwo Jima to Saipan. Behind APA-96 and Zig-zagging.	1945 - Steaming in company with Task Unit 51.16.10.	1945 - Personal effects of Don Bowman (KIA) and Norman Richard (KIA) are transferred from ship.	1945 - Wounded Marine dies on Ship. 1946 - Many leave the Lowndes (see below *).	1945 - Patients unloaded to Guam Hospital. Left Guam for Saipan.	
7	8	9	10	11	12	1.
1945 - Zig-zagging into Saipan.	1945 - Arrived at Saipan and loaded Marines and Cargo (10th Regiment 2nd Marines).	1945 - More Marines loaded at Saipan.	1945 - Tested main fire pumps. Tested general and gas alarms.	1945 - Personal effects of F. Albert transferred. E. Finch transferred (both wounded on Iwo Jima).	sounded from Fighter Command, Saipan.	1945 - Personal effects of D. Clark and D. Easter transferred (both wounded on Iwo Jima).
14	15	16	17	18	19	20
1945 - More Marines loaded at Saipan.	1946 - William Taylor, Herbert Kears, and Sherwood Johnson leave the Lowndes.	1945 - More Marines loaded at Saipan. 1946 - D. Bartlett gets Navy Commendation .	1945 - Mechanical Problems (Leak). Landing Rehearsals at Saipan.	1945 - Out to sea for inspection of turbine and reduction gear and estimate damages.	boiler.	1945 - J. Bussard, E. Morton, and N. Treanor still wounded or missing (from Iwo Jima).
21	22	23	24	25	26	2'
1945 - Loaded all boats except boat #10.	1945 - Collision avoided with APA-196.	1945 - Bensie, Bernardi, and Dinis join Lowndes. 1946 - R. Shy, and Harold Castine leave Lowndes.	1945 - 7 new sailors join the Lowndes for duty.	1945 - Dawson Mims arrives on Lowndes. 1946 - Left Hampton Rds to Norfolk, Virginia.	Telephone service from the	1945 - Headed to Okinaw from Saipan. 1946 - Moved to new birt #35.
28	29	30	31			
1945 - Mail delivery from DD-802.	1946 - Unloaded all ammunition. Port boom falls damaging ship.	1945 - Submarine detected. 1946 - Leland Snider is detached this day.	1945 - Pumped bilges. Performed emergency turns.			
* H. Brunner, W. Harrendorf, H. Mcnamee, D. Scovello, I. Sneed, H. Workman leave Lowndes.						

		U.S.S. L()WNDES (A	APA-154)	12 P	
TAG		A	PRIL 200	4		
		The	e Ship's History Caler www.usslowndes.net	ndar	E	HE
Sunday	Monday	Tuesday	Wednesdav	Thursday	Friday	Saturday

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				1 1945 - Arrived at Okinawa and debarked demonstration troops.	2 1945 - Fired at Jap Bomber. Embarked troops 1946 - Back to Hampton Roads, VA.	3 1945 - Made emergency turn to avoid possible enemy submarine.
4 1945 - More submarine contacts reported. Zig-zagging.	5 1945 - Continued Zig-zagging in Okinawa area.	6 1946 - Underway to Craney Island fuel dock to commenced defueling. Back to Hampton Roads.	ship drills. More	8 1945 - Fire drills and zig-zagging at Okinawa.	9 1945 - Marine stabbed on ship in fight. 1946 - All Boats transferred from Lowndes	10 1946 - Moved to Pier #5 berth #35, Portsmouth, Virginia. APA-159 on port side, APA-101 other
1946 - Many leave Lowndes (* see below).	1945 - Smoke boats away. Boat #20 (Ed King's boat) catches on fire. Enemy Aircraft in area.	13 1945 - Fired on Enemy plane. Debarked Const. Battalion, 2nd Dukw, and 18th field Depot.	14 1945 - Enemy Aircraft in area at Okinawa. Left Okinawa for Saipan.	1945 - Half Masted to honor F. D. Roosevelt. 1946 - Debarked all crew and officers.	16 1946 - Fire on APA-101 (next to Lowndes).	1946 - Many detached from Lowndes (** see below). Decommissioning ceremony. End Decklog.
18 1945 - Arrived at Saipan and lowered Captain's gig.	1945 - Debarked troops at Saipan.	20 1945 - Lowndes collides with a tanker (minor damage).	21 1945 - C. Fesi injured (compound fracture) in boat accident (boat #15).	22 1945 - Court Martial for A. Manzanna (forgery of censor's initials on letter).	23 1945 - Found drifting LCVP from APA-206.	24 1945 - J. Dalton and L. Goldstein transferred for medical treatment.
25 1945 - Anchored in Berth L-57, Saipan Harbor.	26 1945 - General Drills Exercises.	27 1945 - Battle Problem.	28 1945 - Loaded stores at #4 Hatch. Ship turned 180 degrees.	29 1945 - More stores loaded into #4 Hatch at night with use of cargo lights.	30 1945 - Away all Boats at Saipan (Practice).	* F. Brinkman, W. Flagg, H. Leick, C. Martin, E. Mckellar, H. Moore, and W. Ramsey leave.
** L. Bandzak, V. Bardenhagen, E. Bensie, J. Bernardi, J. Cary, H. Chappell, O. Collins,		** J. Gatewood, J. Hess, S. Hornsby, H. Hughes, J. Lackey, J. Lane, J. Layton, H. Lemley,	** D. Long, D. Lorenzi, C. Loseman, W. Markus, L. Mcguire, M.Mehringer, E. Myers, E. Niemi,	** L. O'Brien, R. Papenhausen, B. Piercy, A. Rauseo, W. Riley. C. Ringo, R. Risa, J. Ross,		** W. Schew, J. Zinkgraf

U.S.S. LOWNDES (APA-154) MAY 2004 The Ship's History Calendar www.usslowndes.net							
Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
						1945 - Lowered all boats and debarked Beach Party for exercises on beach.	
2	3	4	5	6	7	8	
1945 - Lowered boats and reembarked Beach Party.	1945 - Full Landing Exercises at Saipan	1945 - Full Landing Exercises at Saipan.	1945 - All boats away except 2 LCM's and "R" boat.	1945 - Saipan: Lit up #1 boiler. Let fires die under #2 boiler.	1945 - Lt. Hardy takes 10 officers and 98 enlisted personnel off ship for anti-aircraft training.	1945 - Anchored in Berth LOVE-57, Inner Saipan Harbor. Men return from training.	
9	10	11	12	13	14	15	
1945 - Completed dock trials and jacked main engines over by steam.	1945 - Lt. (jg) Robert Dunbar accepts temporary appointment to Lt. (MC).	1945 - Anchor on coral bottom with 75 fathoms of chain at Saipan.	1945 - Commanding Officer makes material inspection of upper deck spaces.	1945 - Air Alert Saipan. Ship darkened. Lowered 2 smoke boats. All Clear.	1945 - Emergency battle circuit in operation. Completed loading ammunition.	1945 - Left Saipan harbor to mid-channel. Commenced loading units of 2nd Marine Division.	
16	17	18	19	20	21	22	
1945 - Continued loading Marine cargo. Left Berth A-7, Tanapag Harbor, back to L-57.	1945 - Engine room on 2 hour notice.	1945 - Exercised at Fire Quarters. Fire and Rescue party from APA-121 came aboard.	1945 - Left L-57 to Pier A-6. O. Smith injured and treated by Lt. (Dr.) Dunbar. Marines debarked.	1945 - Continued unloading Marine cargo. Returned to L-57.	1945 - Pumped fresh water to LST-446.	1945 - Lt. Pinnell was detached from the Lowndes this day.	
23	24	25	26	27	28	29	
1945 - LST-708 comes along side and takes 30,100 gallons of fresh water.	Anchored in Berth L-57, Inner Saipan Harbor.	Completed collision, diving, and fire drills and tested all emergency diesel fire pumps.		1945 - YO-174 comes along side and receives 2,420 gallons of diesel oil.	1945 - M. Guerry leaves the Lowndes. LST 758 moored along side for water.	1945 - Lowered boats and completed boat group exercises.	
30 1945 - Completed boat group exercises.	31 1945 - Completed boat group exercises. All boats back aboard except duty boats.						

	U.S.S. LOWNDES (APA-154) JUNE 2004 <i>The Ship's History Calendar</i> <i>www.usslowndes.net</i>						
Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
		1 1945 - All boats participate in exercise waterbourne. Captain inspects below decks.		3 1945 - Anchored in berth L-57, Inner Harbor, Saipan Island.	4 1945 - Pumped water to LST-25. Left Saipan and into open sea. APA-33 is formation guide.	5 1945 - Headed from Saipar to Tulagi. Completed tactical and gunnery exercises.	
6 1945 - Completed tactical and gunnery exercises. USS Logan now the O.T.C.	7 1945 - Exercising at tactical maneuvers. APA-176 is temporary O.T.C.	8 1945 - Commenced tactical maneuvers and zig-zagging.	9 1945 - Davy Jones comes aboard ship to appear before the Royal Court. He leaves ship at 1440	1945 - Neptunus Rex & Royal Court. More	1945 - Steaming at standard speed and zig-zagging.	12 1945 - Entered Port Purvis Florida Island, Berth 19. YO 120 loads Lowndes wit fuel oil.	
13 1945 - Left Berth 19 at Port Purvis headed to Berth 28, Gavatu Harbor. Loaded Ammunition.		1945 - Took aboard 2 LCVP's and 2 LC(S)'s from Naval Base, Tulagi for transport.	16 1945 - Left Tulagi for Espiritu Santo, New Hebrides Islands.	1945 - In group of USS Bayfield, Hendry, Sibley, Kershaw, Newberry, Barrow, Mifflin.	18 1945 - Arrived at Berth #4, Segond Channel, Espiritu Santo.	1945 - Received 3,647 gallons of diesel oil. Loade 27,468 gallons of fuel from YO 20.	
20 1945 - Anchored as before. Lit off #2 boiler and secured #1 boiler.	21 1945 - Commendation ceremonies for Fred Brinkman, Wes Follett, and Jerome Frieder.	22 1945 - Main power generators down for repair. APA-118 guarding radio channels during fix.	23 1945 - Moved from Berth #4 of Segond Channel to Pier #4. Commenced loading cargo.	24 1945 - W. Mathis, certified to be drunk and disorderly by Lt. Dunbar, confined to the ship's brig.	25 1945 - Received fuel. Loaded cargo in holds # 2, 4, and 5. All boats aboard except those at #4 hatch.	26 1945 - All boats aboard and secured for sea. Left Espiritu Santo for Guam.	
27 1945 - Headed to Guam and zig-zagging. Exercised drills. Passed LST's 797 and 449.	e	29 1945 - Simulated steering casualty and shifted control to after steering station.	30 1945 - Passed convoy of LST's 609, 662, 377, 283. Passed Liberty Ship S.S. EdgarW. Nye.				

U.S.S. LOWNDES (APA-154) JULY 2004 The Ship's History Calendar www.usslowndes.net							
Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
				1 1945 - Underway from Espiritu Santo Island to Guam. Passed S.S. Edwin Booth.	2 1945 - Daily inspection of Magazines and smokeless powder samples. Observed sunset.	1945 - Increased speed to 71 RPM's (15 knots). Mor zig-zagging. Steaming singly.	
4 1945 - arrived at Apra Harbor Guam. Delivered LCS and 2 LCVP boats that were in cargo.	5 1945 - S.S. Walter Wyman cast off port side. Inspection of medical and sanitary areas completed.	e	7 1945 - Commanding Officer inspected the upper decks James Davenport is detached.	8 1945 - 2nd Naval Construction Battalion is aboard to work in hatch #4 and #5.	9 1945 - Unloaded cargo to LCT 923 and LCT 969. Working party still aboard ship.	1945 - 3300 gallons of water given to LCT 358. \$50,000 comes on Lownd for Crew pay.	
11	12	13	14	15	16	17	
1945 - YO 124 loads Lowndes with 41,454 gallons of fuel oil. Navy Passengers board Lowndes	1945 - Left Guam for San Francisco. Held morning alert. Exercised at Abandon Ship drill.	1945 - Captain completes below deck inspection. Precautionary evening alert.	1945 - More zig-zagging. Passed APA's 107, 26, and 141. Sighted white flare on horizon.	1945 - Passed within 8 miles of Eniwetok Atoll. Daily inspection of magazines and powder.	1945 - Steaming independently using dimmed running lights from sunset to sunrise.	1945 - Headed to San Francisco with dimmed lights (visible for a distanc of 2 miles).	
18	19	20	21	22	23	24	
1945 - Crossed International date line for the 2nd time (received cards for the first time).	1945 - Observed sunset.	1945 - Observed sunrise. Applied left standard rudder to avoid hitting a log. Passed a Liberty ship.	1945 - Executive Officer completes material and personnel inspection.	1945 - Passed abeam to port, a Liberty type vessel at 800 yards. Observed sunset.	1945 - Observed sunset and reduced standard speed to 15 knots (71 RPMs).	1945 - All clocks advance one hour to conform with Plus 9 time zone.	
25	26	27	28	29	30	31	
1945 - Nearing Stateside. "Best cruise we have made to date" - Fred Brinkman's Diary.	1945 - Tested all diesel fire pumps and flushed fire mains.	1945 - Passed under San Francisco Bay Bridge. Arrived at Berth #9 San Francisco Harbor.	1945 - Anchored as before. Engine room on 2 hour notice.	1945 - "Long-await liberty", "There's nothing Stateside can't cure." - Fred Brinkman's diary.	1945 - I. Sneed, and W. Stewart arrive for duty on Lowndes.	1945 - Another Deck cour case. Daily inspections completed.	



U.S.S. LOWNDES (APA-154) AUGUST 2004

The Ship's History Calendar



otice. Conditions I. 9	Harbor.	Wednesday 4 1945 - Receiving salt and fresh water, steam and telephone service from the dock. 17 men AOL.	floating drydock #4, Moore's Drydocks,	AOL. Completed daily	Saturday 7 1945 - Commenced flooding drydock, Ship
otice. Conditions 1. 9	1945 - Moved to Moore's Dry-docks, Oakland and then back to San Francisco Harbor.	fresh water, steam and telephone service from the	1945 - Dry docked in floating drydock #4, Moore's Drydocks,	1945 - 17 men, again, AOL. Completed daily	
1	10		Oakland.	inspection of magazines and smokeless powder.	waterborne and headed to San Francisco harbor.
Pier #36, North San sco Harbor.		11 1945 - 16 men AOL at this time. Receiving power, fresh water, and phone service from dock.	boiler and #1 switch board ship's main power circuit.	2, ,	1945 - THE WAR IS OVER! YO-91 delivers 5,637 barrels of fuel oil to the Lowndes.
ancisco Harbor. Out for timed speed runs.	Pier #45, San Francisco Harbor. Engine room on 2		and Troops of the 86th Division (1500 men of	Jurica, E. Pilchard, N. Porath, and L. Taylor are	2 1945 - Left San Francisco in fog for Eniwetok Atoll
s rank of Lt.	pumps and flushed fire mains. Fire in the Galley	deck inspections. Observed	independently to Eniwetok	0609 and Mustered crew at	21 1945 - Darkened ship except for wake light unt Condition BAKER and Readiness III are set.
ne Zone. Observed	toward Eniwetok Atoll. Completed below deck				
	16 At Anchorage #12, icisco Harbor. Out or timed speed runs. 23 At. Clark Martin rank of Lt. nder. 30 Changed into Minus e Zone. Observed	1617At Anchorage #12, tecisco Harbor. Out or timed speed runs.1945 - Moored port side to Pier #45, San Francisco Harbor. Engine room on 2 hour notice.2324.t. Clark Martin rank of Lt. nder.1945 - Tested all diesel fire pumps and flushed fire mains. Fire in the Galley (pan of grease).3031Changed into Minus1945 - Still steaming alone	161718At Anchorage #12, tecisco Harbor. Out or timed speed runs.1945 - Moored port side to Pier #45, San Francisco Harbor. Engine room on 2 hour notice.1945 - Earl Robertson is detached this day. 2 AOL men retuned by shore patrol.232425t. Clark Martin rank of Lt. nder.1945 - Tested all diesel fire mains. Fire in the Galley (pan of grease).1945 - Commenced above deck inspections. Observed sunset and darkened ship.3031Changed into Minus e Zone. Observed1945 - Still steaming alone toward Eniwetok Atoll. Completed below deck	16171819At Anchorage #12, tecisco Harbor. Out or timed speed runs.1945 - Moored port side to Pier #45, San Francisco Harbor. Engine room on 2 hour notice.1945 - Earl Robertson is detached this day. 2 AOL men retuned by shore patrol.1945 - Embarked Officers and Troops of the 86th Division (1500 men of Patton's third army).23242526.t. Clark Martin rank of Lt. nder.1945 - Tested all diesel fire pumps and flushed fire mains. Fire in the Galley (pan of grease).1945 - Commenced above deck inspections. Observed sunset and darkened ship.1945 - Proceeding independently to Eniwetok Atoll. Observed sunset.3031Changed into Minus e Zone. Observed1945 - Still steaming alone toward Eniwetok Atoll. Completed below deck1945 - Still steaming alone toward Eniwetok Atoll. Completed below deck	1617181920At Anchorage #12, r timed speed runs.1945 - Moored port side to Pier #45, San Francisco hour notice.1945 - Earl Robertson is detached this day. 2 AOL men retuned by shore patrol.1945 - Embarked Officers and Troops of the 86th Division (1500 men of Patton's third army).1945 - W. Gackstetter, J. Jurica, E. Pilchard, N. Porath, and L. Taylor are detached.2324252627t. Clark Martin rank of Lt. nder.1945 - Tested all diesel fire pumps and flushed fire mains. Fire in the Galley (pan of grease).1945 - Commenced above deck inspections. Observed sunset and darkened ship.1945 - Proceeding independently to Eniwetok Atoll. Observed sunset.1945 - Lighted ship at 0609 and Mustered crew at 0745. No absentees.30311945 - Still steaming alone toward Eniwetok Atoll. Completed below deck1945 - Still steaming alone toward Eniwetok Atoll. Completed below deck1945 - Still steaming alone toward Eniwetok Atoll. Completed below deck1945 - Still steaming alone toward Eniwetok Atoll.



U.S.S. LOWNDES (APA-154) SEPTEMBER 2004



The Ship's History Calendar

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
*Angelotti, Bandzak, Bartol,Benson,Born,Broken shire,Brunner,Carson,	*Chasteen,Christian,Cole, Collins,Contreras,H.Davis,		1	2 1945 - Moved to berth K-4 to refuel. Returned to berth 0-7. Loaded 391 bags of mail cargo.	3 1945 - Left Eniwetok for	4 1945 - Traveling with APA-62, APA-117, APA-20, APA-213, APA-98, and APA-188
assumes fleet guide and	6 1945 - Changed course to avoid approaching vessels. Completed Tactical Exercises.	7 1945 - Arrived at Ulithi. at berth #21. Left Ulithi enroute to San Pedro Bay, Leyte, Philippine Islands.	8 1945 - Traveling with APA's 176, 193, 100, 213, 188, 62 and screen USS Bul (DE-402).	1945 - Observed sunrise and turned off running lights.		11 1945 - Arrived at Batangas Bay, Luzon, Philippine Islands.
Division, U.S. Army.	13 1945 - Philippine Islands: Commenced unloading cargo and troops. Left Batangas for Leyte.	14 1944 - Commissioning Ceremony for Lowndes. *Main crew arrives. ** Boat group arrives.	15 1944 - ** More of the 132 member Boat group (Landing Craft Draft) arrives.		1945 - Loaded troops of 1st and 3rd Battalions, 321st Infantry Division, U.S. Army.	18 1945 - Left Letye for Aomori, Japan joined by APA-48 and APA-188.
contacted. The USS	20 1945 - Made daily inspections of magazines and powder. Conditions normal.	21 1945 - Observed sunrise. Completed below deck inspections.	22 1945 - Lighted running and wake light at 1748.	23 1945 - Burning running lights at full brilliancy through night. Made radar land fall of Hachino Jima.		25 1945 - Arrived at Aomori, Japan to take part in initial occupation landings.
Pumped water/fuel to	27 1945 - Pumped water/fuel to LCSs 14, 111, 109. Unloaded cargo. Crewmen charged with looting.	troops to Japan.	29 1945 - Left Aomori for Saipan. Streamed Paravanes. The USS FILMORE breaks-down.	30 1945 - Screen ship Ulvert M. Moore (DE-442) is detached from formation.	.Long,Lorenzi,Loseman,Ma cpherson,C.Martin,Mcguire	1 57 57 57
Snider, L. Taylor, W. Taylor,	* Trevillyan, Turner, Umbarger, Walker, Warnberg, Wurth, J. Young, Golembowski		** Dudash, Kindle, Harrendorf, Hovey, Proctor, Ricks, Ruether,	** R isa,Rizzo,Rodriguez, J. Ross, Schaffer, Scott, Sefers,C. Tate, Tharp, W. Thomas,Vernale,Wanits	*** Brinkman, W. Clarke, J. Davenport, O. Dickson, J. Erlandson, W. Follett, Frieder, J. Hall, Hodgson	*** S. Hornsby, H. Hughes, W. Kautz, H. Kears, W. Markus, Mehringer

No X

U.S.S. LOWNDES (APA-154)

OCTOBER 2004

The Ship's History Calendar www.usslowndes.net



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
					1 1944 - Enroute from Seattle to San Francisco. 1945 - Enroute from Aomori, Japan to Saipan.	2 1944 - Arrived in Frisco. 1945 - Steaming in company with TransDiv 6 and TransDev 43.
3	4	5	6	7	8	9
1944 - Left San Francisco for San Pedro, CA. Passed through anti-submarine nets.		1944 - Shakedown group boards ship and observes the many ship drills. 1945 - Loaded troops.	1944 - More Shakedown drills. Boat #6 lowered. 1945 - Left Saipan for San Francisco.	Pedro Channel.	1944 - Anchored at San Pedro with Long Beach Pier light given as a bearing.	1944 - To sea, Completed shakedown antiaircraft gun practice. Made run on tug and target sled.
10	11	12	13	14	15	16
1944 - More gunnery exercises. Simulated casualties on #1, 20mm gun moved to sick bay.		1944 - To sea for fueling and paravane exercises. 1945 - Captain completes below deck inspections.	1944 - Made steady run at 70 RPM for Engr. data. 1945 - Destination changed to Seattle.	1944 - Completed full power run at 18.75 knots. 1945 - Master gyro out Using magnetic compass.	1944 - LCVP #19 is dropped on deck. Damage to boat and Boom #7. 1945 - Steaming singly.	1944 - G. Dahms, S. Hyde, L. Johnson, C. Munson, an A. Resetar join the Lowndes.
17	18	19	20	21	22	23
1944 - Moored to Pier 4, Berth 42, Terminal Island 1945 - Calls made to APA-28 via flashing light.	1944 - 130 gallons of fresh milk loaded on ship. 1945 - Arrived at Seattle (Kirkland Shipyard).	at Terminal Is. San Pedro.	1944 - Moved to Pier #3, berth #32, San Pedro. 1945 - Navigator Don MacPherson is detached.	1944 - Loaded fresh and dry provisions. 1945 - Received fresh water + steam from dock.	1944 - V. Bardenhagen and J. Chilicote join the Lowndes. Numerous yard workers on ship.	1944 - Left San Pedro for Pearl Harbor. Loaded 2 LCVP's. Completed Gun practice.
24	25	26	27	28	29	30
1944 - Avoided collision with USS Hendry. 1945 - * Many men detached this day.		1944 - Traveling with USS Hendry, Barrow, and Pickens. Completed zig zagging and Gun practice.	1944 - Exercised General Drills & steering casualty. 1945 - D. Stratton is detached this day.	1944 - Ships in columns 1000 yards apart. 1945 - Lt. W. Ramsey takes Electronics training.	1944 - Avoided collision with USS Pickens. 1945 - Mustered crew and made daily inspections.	1945 - Paymaster brings \$85,950.00 in cash aboard for crew pay. A. Resetar is detached this day.
31						
1944 - All boats away. 1945 - W. Bornhorst, W. Davis, and E. Trevillyan are detached this day.		*G. Buck, C. Bull, E. Cole, J. Dinis, W. Follett, J. Frieder, W. Kautz, Laird, D. Mims, H. Ward, Willey				



U.S.S. LOWNDES (APA-154) NOVEMBER 2004

The Ship's History Calendar

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
	1 1945 - Left Lake Washington (Kirkland Shipyard). Arrived at Pier #90, Berth #4, Seattle.	2 1944 - Troops loaded. 1945 - J. Murphy, E. Scott, and J. Young are detached this day.	3 1944 - Debark/Embark off Port Allen Kauai. 1945 - Left Seattle for Samar, Philippine Islands.	4 1944 - Enroute to Makua, Oahu. More boat practice - embarking/debarking. 1945 - Steaming singly.	5 1944 - Anchored in Waianea, Oahu. Left and arrived at Pearl Harbor. 1945 - Passed LSD 12.	6 1944 - D. Stratton and S. Johnson join Lowndes. In Berth X-7, Pearl Harbor. Left for Kahului Harbor.
7	8	9	10	11	12	13
1944 - Lowndes is fleet guide and OTC. Arrived at Kahului Harbor and loaded Army combat equipment.	1944 - Left Kahului Harbor in formation with USS Pickens. Completed landing exercises at Maui.	off Maui. More Landing	1944 - More landings on Maalaea Bay. Left Maui. 1945 - Heavy fog. Time changed to Zone -12.5.	1944 - More Debarking & Embarking Troops and landings at Maui with USS Pickins, Hendry & Barrow	1944 - Unloaded cargo & troops at Kepuhi Beach. 1945 - Increased speed to 17.5 knots to Samar, P.I.	1944 - Returned to Pearl Harbor and loaded food, supplies, and fuel. 1945 - Pumped bilges.
14	15	16	17	18	19	20
1944 - Left Pearl Harbor. Completed gun exercises. 1945 -Heavy rain & wind. Water gets in fuel oil.	1944 - Returned to Maui and loaded supplies + fuel. 1945 - Destination changed to Manila.	1944 - Out to sea with 3 APA's & screening ships. 1945 - Exercised at fire drills. Deck inspections.		1944 - Away Troops in Practice Landings at Maui 1945 - Steam pressure lost. All engines stopped.	1944 - Debarked the Construction Battalion and TransDiv 45 Beach Party.	1944 - Completed drills: Steering casualty, fire, collision, abandon ship, fire rescue and salvage.
21	22	23	24	25	26	27
1944 - At Kahului Harbor. 1945 - Arrived at Manila Harbor, moored next to USS WINCOSKI (AO-38).	1944 - Attack training. Anchored at Maalaea Bay. 1945 - Completed loading passengers bound for U.S.	1944 - Attack training at Maalaea Bay, Maui. 1945 - Enroute to U.S. Total passengers: 1782.	1944 - Attack training at Maalaea Bay, Maui 1945 - Returned to Manila to avoid a storm.	1944 - Loaded cargo and troops of the 24th Marines, 3rd Battalion. 1945 - In Manila Harbor.	1944 - PC-569 delivers injured for treatment. 1945 - Left Manila for San Francisco.	1944 - Attack training at Maui and gun practice. 1945 - Passed San Bernardino Island.
28	29	30				
1944 - Attack training at Maalaea Bay. LST-928 brings man aboard for examination.	1944 - Back to Pearl Harbor with other ships. 1945 - Traveling singly from Manila to U.S.	1944 - R. Brubaker joins the Lowndes. Observed USS Tolland aground. 1945 - Sighted Saipan.				



U.S.S. LOWNDES (APA-154) DECEMBER 2004



The Ship's History Calendar

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1	2	3	4
			1944 - * Many join the Lowndes this day. 1945 - Enroute to San Francisco.	1944 - Moored in Berth C-5, Pearl Harbor. 1945 - Passed USS Dickens (APA-161).	1945 - Leak in economizer. Stopped all engines. Lost but restored Gyro operation.	1944 - Still Moored in Berth C-5 Pearl Harbor. 1945 - Traveling alone. Passed AP-156.
5	6	7	8	9	10	11
1944 - YO-231 delivers diesel oil to Lowndes. 1945 - Passed Merchant and LSV #4 on starboard.	1944 - Mustered crew at Quarters. No absentees. 1945 - Ship's time changed 24 hours to +11.5 zone.	1944 - Honolulu USO Troupe comes aboard. 1945 - Sighted PCE 893 giving a distress signal.	1944 - A. Gaspard and W. Pollock join the Lowndes. 1945 - Traveling alone. Pumped ballast.	1944 - In Berth B-24, Southeast Lock, Pearl Harbor. Loaded stores. 1945 - Observed sunset.	1944 - Both boilers shut down to repair valve leak. 1945 - Passed AP-102 and APA-46.	1944 - Out to sea again with APA's 196, 207, and 158. Completed tactical maneuvers + gun practice.
12	13	14	15	16	17	18
1944 - Depth Charges dropped ("Embarrassing" incident.) 1945 - Passed USS Refuge	1944 - LST/LSM Towing exercises. 1945 - Arrived at Pier 15, San Francisco.	1944 - Gun practice and LST/LSM Towing and Lowering/Raising Boats exercises. Antisub screen.	1944 - Paravane Exercises. 1945 -In Navy Anchorage #12, Berth #9, Frisco.	1944 - Completed Boat Lowering/Raising exercises in Cruising disposition CHARLIE Form One.	1944 - Lowering/Raising Boats exercises. 1945 - *** Many leave Lowndes this day	1944 - Lowering/Raising Boats exercises 1945 - L. Fougnies is detached this day.
19	20	21	22	23	24	25
1944 - Fueled Destroyer 656. Captain takes Gig. 1945 - **** Many leave Lowndes this day	1944 - Fueled Destoryer 656. Paravane Accident. 1945 - LCT 1449 unloads stores to the Lowndes.	1944 - Exercised at GQ. Completed gun practice. 1945 - O. Dickson and R. Trafton leave Lowndes.	1945 - Dick Jones losses 3 fingers when hand crushed between boat & barge. He leaves the ship this day.	1944 - ** Many join the Lowndes this day. Moored between APA's 207 +158. 1945 - Loaded ballast.	1944- Secured all power for overhaul. 1945 - ***** Many detached from Lowndes.	1945 - Loaded supplies from LCT 1449. Observed sunset. Executed evening colors.
26	27	28	29	30	31	
1944 - Loaded stores. 1945 - Developed leak in main steam line. Welder boards to fix leak.	1944 - Herman Leick joins the Lowndes today. 1945 - Heading to Manila. D. Johnson is detached.	5 5	1944 - Loaded ammo, fuel, money, and Combat Team 23rd 4th Marine Division.	1944 - Moored to pier #2, Kahului Harbor, Maui. Loaded cargo including 1800 lbs of Lettuce.	1944 - Received 23,890 gallons of fresh water. 1945 - Deck court held. Gyro is corrected.	
* J. Gatewood, Fred Groh, W. Robinson, G. Tuppan, William Ward, Harley Workman, J. Zinkgraf.	** Gordon Buck, Calvin Bull, Jack Laird, Harold Ward, Frank Willey.	*** Rex Chapman, Harry Contreras, J. Douthitt, Allan Gaspard, Ivan Hall, F. Judnitsch, Ed King.	*** George Dudash, Joel Rodriguez, Gernard Tracz.	**** Russell Brubaker, George Dahms, Stuart Hyde, Charles Munson.	***** P. Angelotti, James Holderman, W. Kautz, W. Robinson, Jack Tharp, William Thomas.	